HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER CAL 15-BORDNIV, BA.

X-15 Engine Test Complex,
Rocket Engine and Complete X-15
Vehicle Test Stands
Edwards Air Force Base
Rogers Dry Lake, East of Runway
between North Base and South Base
Boron Vicinity
Kern County
California

HAER No. CA-235-A

David G. De Vries, photographer

October, 1997

Note: Photographs CA-235-A-1 through CA-235-A-5 are $8" \times 10"$ enlargements from $4" \times 5"$ negatives.

CA-235-A-1	ROCKET ENGINE TEST STAND, LOCATED IN THE NORTHEAST $\frac{1}{4}$ OF THE X-15 ENGINE TEST COMPLEX. Looking northeast.
CA-235-A-2	ROCKET ENGINE TEST STAND, SHOWING TANK (BUILDING 1929) AND GARAGE (BUILDING 1930) AT LEFT REAR. Looking to west.

	TEST STAND, LOCATED IN SOUTHEAST
⅓ OF X-15 ENGINE TEST	COMPLEX. Looking northeast.

CA-235-A-4								
	COMPLETE	X-15	VEHICLE	TEST	STAND,	DETAIL	OF	THRUST
	MOUNTING	STRU	CTURE AT	ENGI	NE END	OF PLAN	Ε.	

CA-235-A-5	FLAME DEFLECTOR,	COMPLETE X-	-15 VEHI	CLE TEST	STAND.
	Looking east.				

Note: Photographs CA-235-A-6 through CA-235-A-8 are 8" x 10" enlargements from 4" x 5" negatives. These views are photocopies of recent resin coated prints made from prints held at the Main Base History Office, Edwards Air Force Base, California. Photographers unknown. Dates and file numbers unknown except where indicated.

CA-235-A-6 AN EARLY VIEW OF THE COMPLETE X-15 VEHICLE TEST STAND. Looking to the northeast.

X-15 ENGINE TEST COMPLEX,
ROCKET ENGINE AND COMPLETE X-15
VEHICLE TEST STANDS
HAER No. CA-235-A
INDEX TO PHOTOGRAPHS (page 2)

CA-235-A-7

COMPLETE X-15 VEHICLE TEST STAND AFTER AN ENGINE FIRE OR EXPLOSION. Wreckage of engine is still fixed in its clamp; X-15 vehicle lies on the ground detached from engine.

CA-235-A-8

X-15 ENGINE TESTING. A color print showing the engine during test firing. View from the rear of the test stand looking northwest.